


Mill Turn Best Practices

Mike Smith
Halliburton Energy Services
mike.smith8@halliburton.com
972-418-4553





Unigraphics[®] NX 2



Premium Partners:



Halliburton Energy Services



HALLIBURTON




HALLIBURTON | Digital and Consulting Solutions




Halliburton Energy Services


HALLIBURTON | Digital and Consulting Solutions



CEMENTING



HSE
Health, Safety & Environment



Mill Turn Best Practices

Mazak MULTI-TASKING





- **What Mazak Multi-Tasking can do for you:**
- Compress lead times - from days to hours
- Reduce lot sizes with no cost penalty - lots of one, or assembly kits
- Improve cash flow - higher frequency shipments
- Reduce part costs - fewer fixtures, tools and FAR LESS LABOR
- Slash non value-added time - multiple setups, handling, and queue time
- Improve part accuracy - no tolerance build-up
- Reduce shop burden - fewer machine tools/space/utilities
- Run "lights-out" - increase cutting time, but not labor costs
- Increase throughput and profitability

What are your M/T Best Practices

- Work Space Requirements
- Defining Tooling
- Organizing NX
- Post Processor Creation and Testing
- Verification
- Communication
- Refining

Mill Turn Best Practices

- What Equipment Should You Buy?
 - Defining the work envelop is critical
 - Work space restrictions
 - Volume requirements



Mill Turn Best Practices

“Do I have to?”



Mill Turn Best Practices



Mill Turn Best Practices



Mill Turn Best Practices



Mill Turn Best Practices


■ Tooling Impacts are HUGE

- You can not program with out first defining tooling
- Should all the machines in the cell have the same tooling?
- Tooling is the second largest cost next to the machines themselves (example 120 pockets x \$500 = \$60,000)
- Tooling changes require reprogramming
- Always maintain tooling packages in NX

Reduce your stress level by dedicating the necessary resources for Tooling

Mill Turn Best Practices

Make a Tool Library and Maintain it



Mill Turn Best Practices

Make the tooling available to everyone

HALWORLD

Enterprise
Search



[HalWorld Home](#) | [Corporate](#) | [ESG](#) | [KBR](#) | [Support Functions](#) | [News](#)



Carrollton Electronic Tool Book

Title	Revision Date
Drawing Tab-Ons	March 17, 2006
Tool Classification Guide	July 29, 2005
Tool ASSY Book	December 27, 2005
A Book	
• AA-AC External Lathe Tools	March 10, 2006
• AD-AX External Lathe Tools	March 10, 2006
B Book	
• BA-BD Internal Lathe Tools	March 10, 2006
• BE-BX Internal Lathe Tools	March 10, 2006
C Book - Milling Cutters	March 17, 2006
D Book - Drilling Tools, Access	March 17, 2006
E Book - Grooving Tools	March 17, 2006
F Book - Taps & Accessories	February 24, 2006
J Book - Threading Tools	March 17, 2006
M Book - Milling Accessories	March 10, 2006
R Book - Reamers & Accessories	January 17, 2006
Turning Insert Book	March 17, 2006
MISC	

Mill Turn Best Practices

Organizing NX

Does this describe your workplace?

1. Needed document takes a long time to retrieve
NX PARTS
2. Needed supplies are difficult to find
MANUALS
3. Space is crowded with books, old documents, or boxes of files
CD'S **HOLDERS** **CUTTERS**
4. Unneeded items are stacked between coworkers
SCRAP
5. Excess inventory on the floor
6. Excess items/machines make it difficult to improve workflow

Mill Turn Best Practices

Organizing NX





“A clean office is a productive office”



Mill Turn Best Practices

Organizing NX


- Remove any unused programming data
 - Program Groups
 - Tooling Groups
 - Geometry Groups
 - Method Groups



Mill Turn Best Practices

Organizing NX

- Naming conventions should be standardized throughout the cell
- Names should describe the operation
- Names can be carried over to the set up instructions
- Defining templates will help



Mill Turn Best Practices

Organizing NX

- Set up instructions should be extracted from the operation names

- RSBLK# represents the starting place in the program to restart a certain tool#

POS.	OFF SET	----- CUT DESCRIPTION -----	RSBLK #
1	001	FACE BFACE 2TMS MAIN_____	N1
3	003	ROUGH TURN OD MAIN_____	N2
4	004	FINISH TURN OD MAIN_____	N3
25	025	RGH GROOVE OD MAIN_____	N4
28	028	FIN GROOVE OD MAIN T28-ID_____	N5
78	78	MILL 15DEG-AT-C270._____	N6
78	78	MILL 15DEG-AT-C90._____	N7
77	77	RGH MILL 30DEG AT-C0._____	N8
77	77	RGH MILL 30DEG AT-C180._____	N9
77	77	RGH MILL CENTER AT C90._____	N10
93	93	FIN MILL CENTER AT-C90._____	N11
93	93	FIN MILL CENTER AT-C270_____	N12
93	93	FIN MILL 30DEG AT-C0._____	N13
93	93	FIN MILL 30DEG AT-C180._____	N14
89	89	MILL1 15-17DEG ANG CBORES MAIN_____	N15
54	54	DRILL CENTER HOLE MAIN_____	N16
99	99	DEBURR HOLE AND SIDES_____	N17
99	99	DEBURR RIGTH SIDE OF PART MAIN_____	N18
99	99	DEBURR LEFT SIDE OF PART MAIN_____	N19
104	104	THREAD MILL .375-16 MAIN_____	N20
4	004	DEBURR FACE-N-OD MAIN_____	N21
		PART TRANSFER 9001 MAIN 2 SUB G59A_____	N22
1	201	FACE BFACE SUB 1TIME_____	N23
3	203	ROUGH TURN OD SUB_____	N24
4	204	FINISH TURN OD SUB_____	N25
25	225	RGH GROOVE OD SUB_____	N26
28	228	FIN GROOVE OD SUB T28-ID_____	N27
78	78	MILL 15DEG-AT-C270._____	N28
78	78	MILL 15DEG-AT-C90._____	N29
77	77	RGH MILL 30DEG AT C180._____	N30
77	77	RGH MILL 30DEG AT-C90._____	N31
77	77	RGH MILL CENTER AT C90._____	N32
93	93	FIN MILL CENTER AT-C90_____	N33
93	93	FIN MILL CENTER AT-C270._____	N34
93	93	FIN MILL 30DEG AT-C0._____	N35
93	93	FIN MILL 30DEG AT-C180._____	N36
89	189	MILL1 15-17DEG ANG CBORES_____	N37
54	54	DRILL CENTER HOLE SUB_____	N38


Post Processor Creation and Testing

- Your largest technical challenge
- Build and test your post processor before going into production
- Allow considerable time for testing
- Use **ONLY** well established vendors to write your posts
- Expect crashes

Mill Turn Best Practices

Post Processor Creation and Testing

- Halliburton Carrollton uses **UG POST Builder**




Mill Turn Best Practices

Post Processor Creation and Testing

- UDE (User Defined Events)
 - Excellent for tough to define G and M codes
 - Draw back is they don't display in verification
 - Documentation is a must!

Threads Specs. For Thread Milling



MT Mori Machines UG UDE's (User Defined Events) Commands

Additional Commands




Open
M85 (DOORS OPEN)
Close
M86 (DOORS CLOSE)



M85 (DOORS OPEN)
M777 (WAIT SYNC CODE)
M80 (TEXT)
M86 (DOORS CLOSE)
M777 (WAIT SYNC CODE)

If the check box is picked, any text entered will be output following the M80



After working on the part in the sub spindle, use this command to return the part to the Main spindle.


```
M777 (WAIT SYNC CODE)
M1
(RETURN PART TO MAIN)
G28 U0.V0.
N?? (RESTART RETURN PART TO MAIN)
(PUT LBB BLANK IN PLACE)
G461 A1.
T??
G362 B-90. D1.
M11 (MAIN CHUCK OPEN)
G04 X5.(DWELL)
(ALIGN CHUCKS)
M45 (MAIN MILLING MODE)
M69 (UNCLAMP MAIN)
G28 H0.(HOME MAIN SPINDLES)
M245 (SUB MILLING MODE)
M269 (UNCLAMP SUB)
G28 H0.(HOME SUB SPINDLE) * 321
G04 X3.0 * 321
M46 (MAIN MILLING MODE) * 321
G28 E0.(HOME SUB SPINDLE) * 361
G58 (G58 A FOR SUB TO MAIN)
M79 (INCLAMP SUB)
M348 (STEADYREST SYNC RELEASE) only if SR
closed
G0 A2.
G1 G98 A0.F20.
M349
M10 (MAIN CHUCK CLOSE)
G04 X5.(DWELL)
M777 (WAIT SYNC CODE)
```

If LBB was previous tool

Mill Turn Best Practices

Post Processor Creation and Testing


- Some examples of simple to complex UDE's we use daily



Select_Spindle

Status: MAIN

OK Back Cancel



Chuck Jaws

Type: Skip

Main chuck OD
 Main chuck ID
 Main chuck pressure Status


Main chuck pressure: 350

Main use center
 Sub chuck OD
 Sub chuck ID
 Sub chuck pressure Status

Sub chuck pressure: 300

Sub use center

OK Back Cancel



Mori Thread Mill

Thread Type: UN

Thread Diameter: 0.0000

Thread Pitch: 0.0000

Thread Length: 0.0000

Insert Length: 0.0000

X Location: 0.0000

Y Location: 0.0000

Z Location: 0.0000

Clear Feature: 1.0000

Rotary Location: 0.0000

B-axis Rotation (MT): 0.0000

SFM: 0.0000

Approach IPM: 0.0000




Feed Per Tooth: 0.0000

OK Back Cancel

Mill Turn Best Practices

Verification

- Verification is vital during the testing of new post processors



Mill Turn Best Practices






Verification

- UDE's are not visible during verification
- Finding G and M codes that are incorrect is very time consuming and almost impossible in some cases
- 137 pages of code = 130,690 characters
- **FIND THE BAD G CODE**

```
X-.0175 Y.94  
X-.0013 Y.9322  
X.018 Y.9265  
G0 X.0189 Z1.2389  
G40  
G0 X-.9672 Z-1.1407 (PROGRAM CRASH)  
M269 (UNCLAMP SPINDLE)  
GO C319.75  
M268 (CLAMP SPINDLE)|  
GO X-1.6468 Y-.0974 Z1.5847  
Z.5018  
G41 G1 G99 X-1.648 Y-.0965 Z.5017 F.002  
X-1.6592 Y-.084 Z.5004
```

Mill Turn Best Practices

Verification



Mill Turn Best Practices

Communication

- Creating a team for startups works best
- These should include a machine operator, a programmer and the post writer
- Everyone should experience running the machine
- Learn the M and G codes

Mill Turn Best Practices

Communication

- Providing a terminal at the machine is a priority
- Use the functionality inside of NX to create a useful setup sheet
- A level of confidence between the team is essential
- Would you run your own programs?

Mill Turn Best Practices

Communication

“Trust me, I figured out the problem this time”




Mill Turn Best Practices

Refining

- This takes patience, be sure your schedule allows adequate time for tune ups
- Expect setbacks
- Start simple
- Speed will come after the process is developed



Mill Turn Best Practices

Mori Seiki Sub Spindle





Mill Turn Best Practices

Mori Seiki Sub Spindle



Mill Turn Best Practices

Vericut



Mill Turn Best Practices

Please help in thanking the following contributors:

Celso Garza

David Rios

David Wright

Doug Townzen

Greg Jeffers

Greg Mandrell

Jimmy Nelson

Larry Leonhart

Les Ingram

Lynsey Ritchie

Monty Hubbard

Pedro Ayala

Robert Obergfoll

William Murray

Dona Smith

Jon Jarrett

Mark Rief

PLM World